# Oil Field Environmental Incident Summary

**Responsible Party:** ARROW WATER, LLC **Well Operator:** ARROW WATER, LLC

Well Name: THOMPSON 1-SWD

Field Name: BLUE BUTTES Well File #: 90131

Date Incident: 7/8/2014 Time Incident: 11:44 Facility ID Number: 700109-01

County: MCKENZIE Twp: 150 Rng: 95 Sec: 20 Qtr:

Location Description: RELEASE PREVIOUSLY REPORTED TO ND DEPT of HEALTH ON

07/08/2014 (Lat. 47.784727N, Long. -102.643973W)

Submitted By: Don Butler Received By:

Contact Person: Don Butler

c/o Crestwood Midstream Partners LP 801 Cherry StreetSuite 3800/Unit 20

Fort Worth, TX 76102

General Land Use: Badlands Terrain Affected Medium: Soil and Water

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No Reported to NRC: Yes

Spilled Units Recovered Units Followup Units

Oil

Brine 24000 Barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Water courses, plants, wildlife

Areal Extent:

Approx. 8,240-ft in length

## Potential Environmental Impacts:

Water courses, plants, wildlife

#### Action Taken or Planned:

Release halted and contained, control countermeasures deployed, remedial measures ongoing.

Wastes Disposal Location: Permitted facilities

Agencies Involved: ND Department of Health, BIA/BLM, TAT Environmental, MHA Energy, MHA

Homeland Security and Emergency Response, McKenzie County Emergency

Management, NRC, EPA

# **Updates**

Date: 7/8/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

7/8/14 - 15:30 +/- on location at invitation of MHA Environmental. Water in drainage down slope of road was at 216,000 uS/cm. MHA is in the lead on this. US EPA OSC Pete Stevenson is deploying to location 7/9/2014.